

 National Transportation Safety Board FOREIGN NOTIFICATION AVIATION		NTSB ID: DCA11RA092		Most Critical Injury: Serious	
		Occurrence Date: 07/30/2011		Investigated By: Foreign	
		Occurrence Type: Accident			
Location/Time					
Nearest City/Place Georgetown		State	Zip Code	Local Time 0525	Time Zone UTC
Aircraft Information					
Registration Number 9Y-PBM		Aircraft Manufacturer BOEING		Model/Series Number 737/800	
Type of Aircraft: Airplane			Amateur Built Aircraft? No		
Injury Summary:		Fatal	Serious 1	Minor	None 161
Revenue Sightseeing Flight:			Air Medical Transport Flight:		
Narrative					
<p>Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:</p> <p>*** Note: The foreign authority was the source of this information. ***</p> <p>On July 30, 2011, at 1:25 am local time (0525 UTC), a Boeing 737-800, Trinidad & Tobago registration 9Y-PBM, operated by Caribbean Airlines as flight 523, overran the runway upon landing at Cheddi Jagan International Airport, Georgetown, Guyana. Of the 156 passengers and six crew on board, there was reportedly one serious and multiple minor injuries. Weather was reported as raining at the time of the accident. Preliminary details from local authorities indicate that the airplane fractured in two pieces as a result of the overrun. The flight was a scheduled passenger flight from Piarco International Airport, Port of Spain, Trinidad & Tobago.</p> <p>The accident is being investigated by the Guyana Civil Aviation Authority (CAA). The NTSB has designated a U.S. Accredited Representative as the state of manufacture. All inquiries should be directed to the Guyana CAA at:</p> <p>Civil Aviation Authority Fairlie House Lot 96 Duke St Kingston Georgetown Updated on Aug 9 2011 7:39AM</p>					
FOREIGN INFORMATION - SUBJECT TO CHANGG					